


G100



Drevsatser

Z1/Z2

A10/99 - 0.8	504801001/504801101
A12/73 - 1.0	504799402/504801301
A12/97 - 0.8	504801002/504801102
A13/55 - 1.25	504799601/504801501
A13/96 - 0.8	504801003/504801103
A14/71 - 1.0	504799403/504801302
A15/41 - 1.5	504799802/504801701
A15/53 - 1.25	504801402/504801502
A16/69 - 1.0	504801203/504801303
B19/29 - 1.75	504801802/504801902
B19/37 - 1.5	504799805/504801702
B25/43 - 1.25	504801403/504801503

Z3/Z4

11/61 - 1.25	504771601/504771701
12/60 - 1.25	504771602/504771702
17/55 - 1.25	504771603/504771703
20/52 - 1.25	504771604/504771704

Utgående axel(mm): 25 x 42 alt. 25 x 60
 Flänslagerhus: yttre diameter(mm) 140 alt. 160 alt. 200
 Fothus: Mått till axelcentrum 100mm